

# VOLTAGE/CURRENT CALIBRATOR

*Model : CC-421*



# TABLE OF CONTENTS

1. FEATURES.....	1
2. SPECIFICATIONS.....	1
2-1 General Specifications.....	1
2-2 Electrical Specifications.....	2
3. FRONT PANEL DESCRIPTION.....	4
3-1 Display.....	4
3-2 Function Switch.....	4
3-3 Power Switch.....	4
3-4 Range Switch.....	4
3-5 Calibration Adjust knob.....	4
3-6 Battery Compartment/Cover.....	4
3-7 Input Socket.....	4
3-8 Cable Plug.....	4
3-9 Alligator Clips.....	4
4. MEASURING PROCEDURE.....	5
4-1 Current source .....	5
4-2 Current measurement.....	5
4-3 Power and current measurement of two wire loop.....	6
4-4 DC mV source.....	7
5. REPLACEMENT OF BATTERY.....	8

## 1. FEATURES

- \* Portable instrument for calibrating process devices and measuring process signals.
- \* Adjustable 0-24 mA current source.
- \* Adjustable -199.9 mV to +199.9 mV DCV source.
- \* Current calibrator drives loads up to 500 ohms.
- \* The instruments Powers or Measure a two-wire current loop.
- \* Four function provide the quality and accuracy of handheld calibrator : 1) Precision current source, 2) Measurement of a current signal, 3) Power and measurement of two wire loop, 4) Precision DC mV source,

## 2. SPECIFICATIONS

### ***2-1 General Specifications***

Display	LCD display, max. display counts 1999. 13 mm ( 0.5" ) digit size.
Function	<i>1) Current source :</i>
Range & Resolution	2 ranges : 0 - 19.99 mA x 0.01 mA 0 - 24 mA x 0.1 mA
	<i>2) Current measurement :</i>
	2 ranges : 0 - 19.99 mA x 0.01 mA 0 - 24 mA x 0.1 mA
	<i>3) Power and current measurement of two wire loop :</i>
	0 - 19.99 mA x 0.01 mA 0 - 24 mA x 0.1 mA
	<i>4) DC mV source :</i>
	- 199.9 mV to + 199.9 mV x 0.1 mV

Sampling Time	Approx. 0.4 second.
Over input Indication	Indication of " 1 ".
Operating Temperature	0 蛎 to 50 蛎 ( 32 蚌 to 122 蚌 ).
Operating Humidity	Less than 80% RH.
Power Supply	006P DC 9V, MN1604/PP3 battery or equivalent. <i>Alkaline type or heavy duty type.</i>
Power Consumption	<i>Current measurement :</i> Approx. DC 12 mA
	<i>Power and current measurement :</i> Approx. DC 12 mA
	<i>Current source (under 10 mA signal out put) :</i> Approx. DC 33 mA
	<i>DC mV source (under 100 mV signal out put) :</i> Approx. DC 33 mA
Dimension	185 x 78 x 38 mm ( 7.3 x 3.0 x 1.5 inch ).
Weight	265 g/0.58 LB ( including battery ).
Accessories Included	Operational manual..... 1 PC. Cable with the alligator pairs ( red & black ), LN-TL421..... 1 PC.

### ***2-2 Electrical Specifications (23 5 蛎)***

<b>Current source</b>		
Range	Display Resolution	Accuracy
0 - 19.99 mA	0.01 mA	( 0.25 % FS + 1 d )
0 - 24 mA	0.1 mA	( 0.5 % FS + 1 d )
* <i>Output 0 to 24 mA current for loads up to 500 ohms.</i>		
* <i>Output &gt; 20 mA current for loads up to 400 ohms.</i>		
* <i>FS : full scale</i>		

<b>Current measurement</b>		
Range	Display Resolution	Accuracy
0 - 19.99 mA	0.01 mA	( 0.25 % FS + 1 d )
0 - 24 mA	0.1 mA	( 0.5 % FS + 1 d )
* FS : full scale		

<b>Power and current measurement of two wire loop</b>		
Range	Display Resolution	Accuracy
0 - 19.99 mA	0.01 mA	( 0.25 % FS + 1 d )
0 - 24 mA	0.1 mA	( 0.5 % FS + 1 d )
* Provides power DC 12V 2 V to the loop and measures current.		
* FS : full scale		

<b>DC mV source</b>		
Range	Display Resolution	Accuracy
- 199.9 mV to + 199.9 mV	0.1 mV	( 0.25 % FS + 1 d )
* Output measured load impedance should > 1 K ohms.		
* FS : full scale		

*Remark :*

*The above specification are tested under the environment RF Field Strength less than 3 V/M & frequency less than the 30 MHz only.*

## **CAUTION**



- \* **The protection for the input terminals ( red & black alligator pairs ) is AC/DC 10V.**
- \* **Any external voltage is prohibited to input to the meter.**
- \* **If input any voltage over 10 volt will harm the meter's internal circuit, supplier will without liability.**

### 3. FRONT PANEL DESCRIPTION

Fig. 1

- 3-1 Display
- 3-2 Function Switch
- 3-3 Power Switch

<b><i>Symbol</i></b> 1 = On    0 = Off
---

- 3-4 Range Switch
- 3-5 Calibration Adjust knob
- 3-6 Battery Compartment/Cover
- 3-7 Input Socket
- 3-8 Cable Plug
- 3-9 Alligator Clips

## 4. MEASURING PROCEDURE

### ***4-1 Current source***

- 1) Install the " Cable Plug " ( 3-8, Fig. 1 ) into the " Input Socket " ( 3-7, Fig. 1 ).
- 2) Slide the " Function Switch " ( 3-2, Fig. 1 ) to the " CURRENT SOURCE " position.
- 3) Slide the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 19.99 mA " position for getting the 0.01 mA display resolution ( max. display is 19.99 mA ). Slide the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 24.0 mA " position for getting the 0.1 mA display resolution.
- 4) Adjust the " Calibration Adjust knob " ( 3-5, Fig. 1 ) will generate the current output same as the display value.

### ***Note :***

***The " Red Alligator clip " ( 3-9, Fig. 1 ) is for the positive current output. The " Black Alligator clip " ( 3-9, Fig. 1 ) is the " ground " for current output.***

### ***4-2 Current measurement***

- 1) Install the " Cable Plug " ( 3-8, Fig. 1 ) into the " Input Socket " ( 3-7, Fig. 1 ).
- 2) Slide the " Function Switch " ( 3-2, Fig. 1 ) to the " mA MEASURE " position.
- 3) Slide the the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 19.99 mA " position for geeting the 0.01 mA display resolution ( max. display is 19.99 mA ). Slide the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 24.0 mA " position for getting the 0.1 mA display resolution.
- 4) Open the circuit in which current is to be measured and connect the " Alligator Clips " ( 3-9, Fig. 1 ) securely in series with the load in which the current is be measured.

**Note :**

**The " Red Alligator clip " ( 3-9, Fig. 1 ) is for the positive current measurement input. The " Black Alligator clip " ( 3-9, Fig. 1 ) is for the negative current measurement input.**

**4-3 Power and current measurement of two wire loop**

meter equivalent block diagram




Fig. 2

- 1) Install the " Cable Plug " ( 3-8, Fig. 1 ) into the " Input Socket " ( 3-7, Fig. 1 ).
- 2) Slide the " Function Switch " ( 3-2, Fig. 1 ) to the " POWER/ mA MEASURE " position.
- 3) Slide the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 19.99 mA " position for getting the 0.01 mA display resolution ( max. display is 19.99 mA ). Slide the " Range Switch " ( 3-4, Fig. 1 ) to " 0 - 24.0 mA " position for getting the 0.1 mA display resolution.
- 4) Open the circuit in which current is to be measured and connect the " Alligator Clips " ( 3-9, Fig. 1 ) securely in series with the load in which the current is to be measured.



**Note :**

- a. **The " Red Alligator clip " ( 3-9, Fig. 1 ) is for the positive current measurement input.  
The " Black Alligator clip " is for the negative current measurement input.**
- b. **The measuring procedures & principal are same as the 4-2 Current measurement except the meter build in the DC 12 V power source in serial with the current meter, please refer Fig. 2.**

**4-4 DC mV source**

- 1) Install the " Cable Plug " ( 3-8, Fig. 1 ) into the " Input Socket " ( 3-7, Fig. 1 ).
- 2) Slide the " Function Switch " ( 3-2, Fig. 1 ) to the " VOLTAGE SOURCE " position.
- 3) Adjust the " Calibration Adjust knob " ( 3-5, Fig. 1 ) will generate the voltage ( mV ) output same as the display value.

**Note :**

**The " Red Alligator clip " ( 3-9, Fig. 1 ) is for the positive voltage output. The " Black Alligator clip " ( 3-9, Fig. 1 ) is for the negative voltage output.**

## **5. REPLACEMENT OF BATTERY**

- 1) When LCD display show the " BAT " marker,  
It is necessary to replace the battery. However,  
in-spec measurement may still be made for several  
hours after low battery indicator appears before the  
instrument become inaccurate.
- 2) Slide the " Battery Cover " ( 3-6, Fig. 1 ) away from the  
instrument by loss the screw and remove the battery.
- 3) Replace with 9V battery ( Alkaline or heavy duty type )  
and reinstate the cover.
- 4) Make sure the battery cover is secured after change the  
battery.